Quick Installation Guide

USB Serial Converter

On Windows 2000/XP/Vista/Win 7

Note: DO **NOT** connect the USB Serial Converter to your computer before completing the driver installation.

1. Insert the provided CD into your CD-ROM drive. Run the **Setup** file under **E:\Driver** where E: is your CD-ROM drive letter. When the welcome screen appears, click **Next**.
2. Click **Finish** to complete the installation.
3. Once the installation is done, connect the converter to a free USB port on your computer.

On Mac OS X

1. Insert the provided driver CD into your CD-ROM drive. Double-click the CD icon on the desktop and navigate to the directory of **\Driver\MacX**. Copy and then paste the **PL2303_1.2.1r2.dmg** file to the desktop.
2. Double-click the dmg file on the desktop to extract the file. Then double-click the **PL2303_1.2.1** file that is extracted.
3. When the welcome screen appears, click **Continue**.
4. Select a destination disk to install the driver and click **Continue**.
5. Click **Install**.
6. When the **Authenticate** screen appears, enter your password in the provided field and click **OK**.
7. Click **Continue Installation**.
8. Click **Restart** to finish installing the driver and reboot your Mac.
9. Connect the converter to a free USB port on your Mac.

Connecting Serial Device

Now you can connect your RS-232 device to the converter. If prompted to install the driver for your serial device, follow the manual that comes with your serial device to complete the installation.

This ***Quick Installation Guide*** describes only the basic instructions on installation. For more information, please refer to the ***User's Manual*** on the provided CD-ROM.